




*Engineering Design  
and Technology Series*

# **An Introduction to Motion Analysis Applications with SolidWorks Motion, Student Workbook**



SolidWorks Corporation  
300 Baker Avenue  
Concord, Massachusetts 01742 USA  
Phone: +1-800-693-9000

Outside the U.S.: +1-978-371-5011  
Fax: +1-978-371-7303  
Email: [info@solidworks.com](mailto:info@solidworks.com)  
Web: <http://www.solidworks.com/education>

© 1995-2010, Dassault Systèmes SolidWorks Corporation, a Dassault Systèmes S.A. company, 300 Baker Avenue, Concord, Mass. 01742 USA. All Rights Reserved.

The information and the software discussed in this document are subject to change without notice and are not commitments by Dassault Systèmes SolidWorks Corporation (DS SolidWorks).

No material may be reproduced or transmitted in any form or by any means, electronic or mechanical, for any purpose without the express written permission of DS SolidWorks.

The software discussed in this document is furnished under a license and may be used or copied only in accordance with the terms of this license. All warranties given by DS SolidWorks as to the software and documentation are set forth in the SolidWorks Corporation License and Subscription Service Agreement, and nothing stated in, or implied by, this document or its contents shall be considered or deemed a modification or amendment of such warranties.

### **Patent Notices for SolidWorks Standard, Premium, Educational, and Professional Products**

U.S. Patents 5,815,154; 6,219,049; 6,219,055; 6,603,486; 6,611,725; 6,844,877; 6,898,560; 6,906,712; 7,079,990; 7,184,044; 7,477,262; 7,502,027; 7,558,705; 7,571,079; 7,590,497; 7,643,027; 7,672,822; 7,688,318; 7,694,238, and foreign patents, (e.g., EP 1,116,190 and JP 3,517,643). U.S. and foreign patents pending.

### **Trademarks and Other Notices for All SolidWorks Products**

SolidWorks, 3D PartStream.NET, 3D ContentCentral, PDMWorks, eDrawings, and the eDrawings logo are registered trademarks and FeatureManager is a jointly owned registered trademark of DS SolidWorks.

SolidWorks Enterprise PDM, SolidWorks Simulation, SolidWorks Flow Simulation, and SolidWorks 2010 are product names of DS SolidWorks.

CircuitWorks, Feature Palette, FloXpress, PhotoWorks, TolAnalyst, and XchangeWorks are trademarks of DS SolidWorks.

FeatureWorks is a registered trademark of Geometric Ltd.

Other brand or product names are trademarks or registered trademarks of their respective holders.

#### **COMMERCIAL COMPUTER SOFTWARE - PROPRIETARY**

U.S. Government Restricted Rights. Use, duplication, or disclosure by the government is subject to restrictions as set forth in FAR 52.227-19 (Commercial Computer Software - Restricted Rights), DFARS 227.7202 (Commercial Computer Software and Commercial Computer Software Documentation), and in the license agreement, as applicable.

Contractor/Manufacturer:

Dassault Systèmes SolidWorks Corporation, 300 Baker Avenue, Concord, Massachusetts 01742 USA

### **Copyright Notices for SolidWorks Standard, Premium, Educational, and Professional Products**

Portions of this software © 1990-2010 Siemens Product Lifecycle Management Software III (GB) Ltd.

Portions of this software © 1998-2010 Geometric Ltd.

Portions of this software © 1986-2010 mental images GmbH & Co. KG.

Portions of this software © 1996-2010 Microsoft Corporation. All rights reserved.

Portions of this software © 2000-2010 Tech Soft 3D.

Portions of this software © 1998-2010 3Dconnexion.

This software is based in part on the work of the Independent JPEG Group. All Rights Reserved.

Portions of this software incorporate PhysX™ by NVIDIA 2006-2010.

Portions of this software are copyrighted by and are the property of UGS Corp. © 2010.

Portions of this software © 2001 - 2010 Luxology, Inc. All Rights Reserved, Patents Pending.

Portions of this software © 2007 - 2010 DriveWorks Ltd.

Copyright 1984-2010 Adobe Systems Inc. and its licensors. All rights reserved. Protected by U.S. Patents 5,929,866; 5,943,063; 6,289,364; 6,563,502; 6,639,593; 6,754,382; Patents Pending.

Adobe, the Adobe logo, Acrobat, the Adobe PDF logo, Distiller and Reader are registered trademarks or trademarks of Adobe Systems Inc. in the U.S. and other countries.

For more copyright information, in SolidWorks see **Help > About SolidWorks**.

Other portions of SolidWorks 2010 are licensed from DS SolidWorks licensors.

#### **Copyright Notices for SolidWorks Simulation**

Portions of this software © 2008 Solversoft Corporation.

PCGLSS © 1992-2007 Computational Applications and System Integration, Inc. All rights reserved.

Portions of this product are distributed under license from DC Micro Development, Copyright © 1994-2005 DC Micro Development, Inc. All rights reserved.

# Introduction

## About This Course

The *Introduction to Motion Analysis Applications with SolidWorks Motion* and its supporting materials is designed to assist you in learning SolidWorks Motion Simulation in an academic setting. It offers a competency-based approach to learning rigid body kinematics and dynamics concepts.

## Online Tutorials

The *Introduction to Motion Analysis Applications with SolidWorks Motion* is a companion resource and is supplemented by the SolidWorks Motion Online Tutorials.

### Accessing the Tutorials

To start the Online Tutorials, click **Help, SolidWorks Tutorials, All SolidWorks Tutorials**. The SolidWorks window is resized and a second window will appear next to it with a list of the available tutorials. As you move the pointer over the links, an illustration of the tutorial will appear at the bottom of the window. Click the desired link to start that tutorial.

### Conventions


Set your screen resolution to 1280x1024 for optimal viewing of the tutorials.


The following icons appear in the tutorials:


[Next](#) » Moves to the next screen in the tutorial.


💡 Represents a note or tip. It is not a link; the information is to the right of the icon. Notes and tips provide time-saving steps and helpful hints.




 You can click most toolbar buttons that appear in the lessons to flash the corresponding SolidWorks button. The first time you click the button, an ActiveX control message appears: An ActiveX control on this page might be unsafe to interact with other parts of the page. Do you want to allow this interaction? This is a standard precautionary measure. The ActiveX controls in the Online Tutorials will not harm your system. If you click **No**, the scripts are disabled for that topic. Click **Yes** to run the scripts and flash the button.

 **Open File** or **Set this option** automatically opens the file or sets the option.


 **Video example** shows a video about this step.

 **A closer look at...** links to more information about a topic. Although not required to complete the tutorial, it offers more detail on the subject.

 **Why did I...** links to more information about a procedure, and the reasons for the method given. This information is not required to complete the tutorial.

### Printing the Tutorials

If you like, you can print the Online Tutorials by following this procedure:

- 1 On the tutorial navigation toolbar, click **Show**  .  
This displays the table of contents for the Online Tutorials.
- 2 Right-click the book representing the lesson you wish to print and select **Print** from the shortcut menu.  
The **Print Topics** dialog box appears.
- 3 Select **Print the selected heading and all subtopics**, and click **OK**.
- 4 Repeat this process for each lesson that you want to print.

## SolidWorks Simulation Product Line

---


While this course focuses on the introduction to the rigid body dynamics using SolidWorks Motion Simulation, the full product line covers a wide range of analysis areas to consider. The paragraphs below lists the full offering of the SolidWorks Simulation packages and modules.

Static studies provide tools for the linear stress analysis of parts and assemblies loaded by static loads. Typical questions that will be answered using this study type are:


Will my part break under normal operating loads?

Is the model over-designed?


Can my design be modified to increase the safety factor?




Buckling studies analyze performance of the thin parts loaded in compression. Typical questions that will be answered using this study type are:  
Legs of my vessel are strong enough not to fail in yielding; but are they strong enough not to collapse due to loss of stability?  
Can my design be modified to ensure stability of the thin components in my assembly?



Frequency studies offer tools for the analysis of the natural modes and frequencies. This is essential in the design of many components loaded in both static and dynamic ways. Typical questions that will be answered using this study type are:  
Will my part resonate under normal operating loads?  
Are the frequency characteristics of my components suitable for the given application?  
Can my design be modified to improve the frequency characteristics?




Thermal studies offer tools for the analysis of the heat transfer by means of conduction, convection, and radiation. Typical questions that will be answered using this study type are:



Will the temperature changes effect my model?  
How does my model operate in an environment with temperature fluctuation?  
How long does it take for my model to cool down or overheat?  
Does temperature change cause my model to expand?  
Will the stresses caused by the temperature change cause my product failure (static studies, coupled with thermal studies would be used to answer this question)?


Drop test studies are used to analyze the stress of moving parts or assemblies impacting an obstacle. Typical questions that will be answered using this study type are:  
What will happen if my product is mishandled during transportation or dropped?  
How does my product behave when dropped on hard wood floor, carpet or concrete?



Optimization studies are applied to improve (optimize) your initial design based on a set of selected criteria such as maximum stress, weight, optimum frequency, etc. Typical questions that will be answered using this study type are:  
Can the shape of my model be changed while maintaining the design intent?  
Can my design be made lighter, smaller, cheaper without compromising strength of performance?

Fatigue studies analyze the resistance of parts and assemblies loaded repetitively over long periods of time. Typical questions that will be answered using this study type are:  
Can the life span of my product be estimated accurately?  
Will modifying my current design help extend the product life?


Is my model safe when exposed to fluctuating force or temperature loads over long periods of time?  
Will redesigning my model help minimize damage caused by fluctuating forces or temperature?




Nonlinear studies provide tools for analyzing stress in parts and assemblies that experience severe loadings and/or large deformations. Typical questions that will be answered using this study type are:  
Will parts made of rubber (o-rings for example) or foam perform well under given load?  
Does my model experience excessive bending during normal operating conditions?



Dynamics studies analyze objects forced by loads that vary in time. Typical examples could be shock loads of components mounted in vehicles, turbines loaded by oscillatory forces, aircraft components loaded in random fashion, etc. Both linear (small structural deformations, basic material models) and nonlinear (large structural deformations, severe loadings and advanced materials) are available. Typical questions that will be answered using this study type are:  
Are my mounts loaded by shock loading when vehicle hits a large pothole on the road designed safely? How much does it deform under such circumstances?



Flow Simulation enables user to analyze the behavior and effect of moving fluids around or within parts and assemblies. Heat transfer in both fluids and solids is considered as well. Pressure and temperature effect can subsequently be transferred into SolidWorks Simulation studies to continue with the stress analysis. Typical questions that will be answered using this modulus are:



Is the fluid moving too fast and will it cause problems in my design?  
Is the moving fluid too hot or too cold?  
Is the heat transfer in my product efficient? Can it be improved?  
How effective is my design at moving fluid through the system?

Composites modulus allows users to simulate structures manufactured from laminated composite materials. Typical questions that will be answered using this modulus are:  
Is the composite model failing under the given loading?  
Can the structure be made lighter using composite materials while not compromising with the strength and safety?  
Will my layered composite delaminate?






## Basic Functionality of SolidWorks Motion

### Active Learning Exercise – Motion analysis of a 4 bar mechanism

---

Use SolidWorks Motion Simulation to perform motion analysis on the 4Bar .SLDASM assembly shown below. The green link is given an angular displacement of 45 degrees in 1 sec in the clockwise direction and it is required to determine the angular velocity and acceleration of the other links as a function of time. Also we will calculate the torque needed to induce this motion as an in class discussion topic.

The step by step instructions are given below.



#### Opening the 4Bar.SLDASM document

- 1 Click **File, Open**. In the Open dialog box, browse to the 4Bar . SLDASM assembly located in the corresponding subfolder of the SolidWorks Curriculum\_and\_Courseware\_2009 folder and click **Open** (or double-click the part).

#### Checking the SolidWorks Motion Add-In

Make sure that SolidWorks Motion Add-In is activated.

To do so:

- 1 Click **Tools, Add-Ins**. The **Add-Ins** dialog box appears.
- 2 Make sure that the check boxes next to SolidWorks Motion are checked.
- 3 Click **OK**.

## Checking the SolidWorks Motion Add-In


Make sure that SolidWorks Motion Add-In is activated.

To do so:

- 1 Click **Tools, Add-Ins**. The **Add-Ins** dialog box appears.
- 2 Make sure that the check boxes next to SolidWorks Motion are checked.
- 3 Click **OK**.

## Model Description


This model represents a typical 4 bar linkage mechanism. The Base part is fixed and cannot move. It always stays horizontal and in real life is fixed to the ground. The other three links are connected to each other and to the base with pins. The links are allowed to hinge about the pins in the same plane and any out of plane motion is prevented. When you model this mechanism in SolidWorks we create mates to put the parts in place. SolidWorks Motion automatically translates these mates into the internal joints. Each mate has several degrees of freedom associated with it. For example a concentric mate has only two degrees of freedom (translation and rotation about its axis). For more details on mates and the degrees of freedom they have please refer to the online help on SolidWorks Motion Simulation.





## Switching to SolidWorks Motion Manager


Switch to SolidWorks Motion by clicking the Animation1 tab in the bottom left hand corner.



SolidWorks Motion takes full advantage of SolidWorks Animator and thus the look and feel of the SolidWorksMotionManager is very similar to that of the SolidWorks Animator.


## Fixed and Moving Components

Fixed and moving components in SolidWorks Motion are determined by their **Fix/Float** status in the SolidWorks model. In our case, Base component is fixed while the other three links are moving.



## Automatic Creation of internal joints from SolidWorks Assembly Mates

The motion of the mechanism is fully defined by the SolidWorks mates.



## Specifying the Input Motion


Next we will define a motion to one of the links. In this example we would like to rotate Link2 by 45 degrees clockwise about the Base. To do this we will impose a rotary motion to Link2 at the location of the concentric mate simulating the pin connection with the Base. The angular displacement needs to be achieved in 1 sec and we will use a step function to ensure that Link2 rotates smoothly from 0 to 45 degrees.

Right click on the **Motor** icon  to open the **Motor** dialog.


Under **Motor Type** select **Rotary Motor**.

Under **Component/Direction** select the cylindrical face of Link2 pinned to the Base (see the figure). Note that the center of the selected cylindrical face also determines the default location of the motor.

Under **Motion** select **Expression**, **Displacement** and enter the following function: **STEP(TIME,0,0D,1,45D)**.



The last three fields under **More Options** are used to change the default motor location, to specify whether the motion is prescribed with respect to another moving component, and to specify the load bearing faces for SolidWorks Simulation stress analysis.



Since we wish to move Link2 with respect to the fixed Base, the first field **Component to move relative to** will be left blank.

Because the default location of the motor, determined by the cylindrical face specified in under **Component/Direction** is correct, **Motor location** field under **More options** will be left blank as well.


Click **OK** to close the **Motor** dialog.

### Motion analysis type

SolidWorks offers three types of the assembly motion simulation:

- 1 **Animation** is simple motion simulation ignoring the components' inertial properties, contacts, forces and similar. Its use is suited for the verification of the correct mates, for example.
- 2 **Basic Motion** offers some level of realism by accounting for the inertial properties of the components for example. It does not, however, recognize externally applied forces.
- 3 **Motion Analysis** is the most sophisticated motion analysis tool reflecting all required analysis features such as inertial properties, external forces, contacts, mate friction etc.


Under **Type of Study** on the left hand side of the SolidWorksMotionManager, select **Motion Analysis**.




### Simulation time

The duration of the motion simulation is driven by the topmost time line in the SolidWorksMotionManager. Because SolidWorksMotion sets the default analysis duration to 5 seconds this parameter needs to be modified.

Move the end time key of the topmost timeline from 5 second to a 1 second location.



## Running the Simulation

In the SolidWorksMotionManager click the **Calculate** icon .

Note the motion simulation during the calculation.

## Looking at the Results



First let us plot the angular velocity and acceleration for Link1.

Click the **Results and Plots** icon  to open the **Results** dialog.


Under **Results** select **Displacement/Velocity/Acceleration, Angular Velocity** and **Magnitude**.

Still under **Results** select Link1. (Note that once a mate or a part is selected, SolidWorksMotion shows the default coordinate system in which the results will be output).

The **Component to define XYZ directions (optional)** field is used to reference our plot results with respect to a local coordinate system of another moving component. To plot the results in the default coordinate system shown in the figure, leave this field empty.




Click **OK** to show the plot.



The above plot shows the variation of the angular velocity of the center of mass for Link1 as function of time.

Repeat the above procedure to plot the **Magnitude** of the **Angular Acceleration** for the center of mass of Link1.




The results indicate the maximum angular velocity and angular acceleration of 6 deg/sec and 38 deg/sec<sup>2</sup>, respectively.

Similarly, create the plots of the angular velocity and angular acceleration at the center of mass for Link2 and Link3.

### Storing and editing result plots

The generated result plot features are stored in the newly created **Results** folder on the bottom of the SolidWorksMotionManager.

Right-clicking on any plot feature allows you to hide and show the plot, as well as edit its settings.




### Create a Trace Path

SolidWorksMotion allows you to graphically display the path that any point on any moving part follows. This is called a trace path. You can create trace path with reference to any fixed part or with reference to any moving component in the assembly. We will create a trace path for a point located on Link1 component.

To create a trace path right click on the **Results and Plots** icon.

In the **Results** dialog select **Displacement/Velocity/Acceleration** and **Trace Path**.


In the first selection field select the circular edge on **Link1** to identify the center point of the circle. The coordinate system graphically shows the point on the screen.



Note that the resulting trace path is by default shown with respect to the fixed ground. To show the trace path with respect to the another moving component, one would have to select this reference component as a second item in the same selection field.

Click **OK** to close the **Results** dialog.

Click the **Calculate** icon to plot the trace path.



This completes your first SolidWorksMotion simulation.

## 5 Minute Assessment

---


1. How do you start a SolidWorks Motion session?
2. How do you activate SolidWorks Motion Add-In?
3. What types of motion analyses are available in SolidWorks?
4. What is analysis?
5. Why analysis is important?
6. What does SolidWorks Motion analysis calculate?
7. Does SolidWorks Motion assume the parts to be rigid or flexible?
8. Why is motion analysis important?
9. What are the main steps in performing motion analysis?
10. What is a trace path?
11. Are Solidworks mates used in SolidWorks Motion model?



## Project — Slider Crank Mechanism

---

In this project you will see how to use SolidWorks Motion to simulate a slider crank mechanism and also calculate the velocity and acceleration of the center of mass of the reciprocating part in the mechanism.



### Tasks

- 1 Open the SliderCrank.sldasm located in the corresponding subfolder of the SolidWorks Curriculum\_and\_Courseware\_2009 folder and click **Open** (or double-click the part).
- 2 Review the fixed and moving parts in the assembly.
- 3 Prescribe uniform 360 deg/sec rotational velocity to the Crank. Make sure that the motion is specified at the BasePart/Crank pin location. (You can enter **360 deg/sec** directly into the **Motor speed** field. SolidWorks Motion then converts the value to RPM).
- 4 Run SolidWorks Motion simulation for 5 seconds.
- 5 Determine the velocity and acceleration of the MovingPart.

**Lesson 1 Vocabulary Worksheet**

---

Name \_\_\_\_\_ Class: \_\_\_\_\_ Date: \_\_\_\_\_

*Directions: Fill in the blanks with the proper words.*

1. The sequence of creating a model in SolidWorks, manufacturing a prototype, and testing it:
2. The method used by SolidWorks Motion to perform motion analysis:
3. The entity that connects two parts and also governs the relative motion between the two parts:
4. How many degrees of freedom does a free body have? :
5. How many degrees of freedom does a concentric mate have? :
6. How many degrees of freedom does a fixed part have? :
7. A path or trajectory that any point on a moving part follows:
8. The trace path of a reciprocating cylinder with respect to the ground represents a:
9. The types of Motion that can be given to a concentric mate:
10. In SolidWorks Motion the movement of gears can be simulated using:
11. A mechanism that is used to transform rotary motion to reciprocating motion:
12. The ratio of the output torque exerted by the driven link to the necessary input torque required at the driver:

**Lesson 1 Quiz**

---

Name: \_\_\_\_\_ Class: \_\_\_\_\_ Date: \_\_\_\_\_

Directions: Answer each question by writing the correct answer or answers in the space provided.

1. How to switch between the SolidWorks Motion Manager and SolidWorks Feature Manager?
2. What types of motion analysis can you perform in SolidWorks Motion?
3. How does SolidWorks Motion automatically create internal joints?
4. How do you assign motion to a part mate?
5. If I want to assign a rotary motion to a part smoothly with a given time then how should I assign the motion?
6. How many degrees of freedom does a point-to-point coincident mate have?
7. What is a trace path?
8. Name one application of trace path?